

#### **MSR** Laboratories

348 Bedford St. Lakeville,

MA 02347

Phone: 781-297-2030 Fax: 877-571-4538 www.msrlabs.com

## Product Report

D (D)	G . 1 . 24 . 2020				
Report Date:	September 24, 2020		FAIL		
Report #:	MISC-200705-003		1 / 1 1		
<b>Submission Information</b>	1				
<b>Submitter:</b>	Center for Strategic Research	ch and			
	Development of Georgia				
<b>Contact Person:</b>	Eka Urushadze				
Address:	5 Jebashvili 1 <sup>st</sup> Exit		A Harman and A	ur.	
City:	Tbilisi				
State:	N/A		00330893		
Zip Code:	0177		9000		
Country:	Georgia		YÜZÜK		
<b>Product Information</b>					
<b>Product Line:</b>	Adult Jewelry – "Yuzuk"				
Style/Item#:	00330893				
<b>Country of Origin:</b>	N/L				
<b>Destination Country(s):</b>	Georgia				
Labeled Age Range:	Not Labeled	1000			
<b>Evaluated Age Range:</b>	Adult				
<b>Product Description:</b>	Gold Ring with Blue Stones				
-		1			
<b>Product &amp; Testing Inform</b>	<u>nation</u>				
<b>Product Type</b>	☐ Raw Materials	☐ Pre-Production	□ Production	☐ Development	
	☐ QC Test	☐ Mock-Up	☐ Digital Image	☐ Failure/Re-Test	
	☐ Design Evaluation	☐ Risk Assessment	☐ Product Testing		
<b>Requested Service</b>	☐ Document Review	☐ Package Review	☐ Other:	,	
	☐ ASTM F963-17		303: Lead in Surface Coat	tings	
Evaluation Standard(s)	☐ Total Lead in Substrates ☐ ASTM F963-17: Soluble Heavy Metals				
	☐ Total Heavy Metals		☐ CPSIA - Phthalates ☐ CPSIA 2008		
	•		al Cadmium in Substrates		

### **Summary & Conclusion:**

At the request of the client testing was conducted on the submitted samples for Total Lead per EU Regulation (EC) No 1907/2006 (REACH) Annex XVII, Entry 63 and Total Cadmium content per the requirements of EU Regulation (EC) No 1907/2006 (REACH) Annex XVII, Entry 23. Testing was conducted with respect to Test Methods CPSC-CH-E1001-08.3 / CSPC-CH-E1002-08.3 (modified to include cadmium) as applicable by material type, on actual finished product as provided. All Tested components meet the applied regulations.

#### © 2019 MSR Quality Management Services, LLC.

The information in this document has been compiled by MSR Quality Management Services, LLC (MSR QMS). The information herein applies only to the specific materials, products or processes examined, evaluated or reviewed and are not necessarily indicative of the qualities of apparently identical or similar materials, products or processes. While every effort has been made to ensure the accuracy of this information, MSR QMS accepts no responsibility for any errors or omissions. The liability of MSR QMS with respect to services rendered shall be limited to the amount of consideration paid for such services and not include any consequential damages. Conformity with the requirements detailed above does not relieve parties of any statutory obligations under the laws of the destination country. This document is the property of MSR QMS and may not be reproduced in part or in whole without the express permission of MSR QMS.



**MSR** Laboratories

348 Bedford St. Lakeville,

MA 02347

Phone: 781-297-2030 Fax: 877-571-4538 www.msrlabs.com

# **Analytical Test Results**

"Yuzuk": Gold Ring with Blue Stones					
Report Number	Sample Description	Cadmium (Limit 100 PPM)	Lead (Limit 500 PPM)		
MISC-200705-003	Metal Stone Holder & Solder	12	2,070		

\*ND - Not Detected

These tests are accredited and meet the requirements of ISO/IEC 17025 as verified by the ANSI-ASQ National Accreditation Board/ANAB. Refer to the MSR-QMS certificate and scope of accreditation (AT-1366).

Regards,

Mark Simonds

**CEO** 

**MSR** Laboratories

Mary Simond

© 2019 MSR Quality Management Services, LLC.

The information in this document has been compiled by MSR Quality Management Services, LLC (MSR QMS). The information herein applies only to the specific materials, products or processes examined, evaluated or reviewed and are not necessarily indicative of the qualities of apparently identical or similar materials, products or processes. While every effort has been made to ensure the accuracy of this information, MSR QMS accepts no responsibility for any errors or omissions. The liability of MSR QMS with respect to services rendered shall be limited to the amount of consideration paid for such services and not include any consequential damages. Conformity with the requirements detailed above does not relieve parties of any statutory obligations under the laws of the destination country. This document is the property of MSR QMS and may not be reproduced in part or in whole without the express permission of MSR QMS.